

LIGHT ELECTRONICS CO., LTD.



DATA SHEET


 SPEC. NO.
 : SZ22110501


 DATE
 : 2022/11/05


 REV.
 : A/0

Approved By: Checked By: Prepared By:

L	LIGHT ELECTRONICS CO., LTD.	












LIGHT ELECTRONICS CO., LTD.










	TOUT	LIGHT ELECTRONICS CO., LTD.
Ca	rier Tape Spec	itications
1 /		
$\parallel \parallel$		
Ш		
1		
Mo	oisture Resistan	t Packaging
1		\sim 1

LIGHT ELECTRONICS CO., LTD.



Suggest IR Reflow Condition For Lead Free




- TIME
- 1. Reflow soldering should not be done more than two times.
- 2. When soldering, do not put stress on the LEDs during heating.

- 1. When hand soldering, the temperature of the iron must less than 300°C for 3 seconds.
- 2. The hand solder should be done only once.

Repairing

Repair should not be done after the LEDs have been soldered. When repairing is unavoidable, a double-head soldering iron should be used (as below figure). It should be confirmed beforehand whether the characteristics of LEDs will or will not be damaged by repairing.



Part No. SL-T1615IRGRC020-L60 Page 10 of 10